IMPORTANT SAFETY RECALL NOTICE - June 13, 2013 ALL Thompson/Center Arms ICON®, VENTURE® and DIMENSION™ rifles manufactured PRODUCT: before June 13, 2013. Thompson/Center Arms has identified a condition where the safety lever in certain rifles may **DESCRIPTION OF** bind preventing the safety from becoming fully engaged. In this situation, closing the bolt may THE HAZARD: move the safety to the fire position. The rifle will not fire unless the trigger is pulled. However, out of an abundance of caution, we are initiating this recall to allow for the prompt inspection and, if necessary, the repair of each rifle. This recall applies to all ICON, VENTURE and DIMENSION rifles manufactured before June 13, **DESCRIPTION OF** 2013. The following is a list of affected models: THE PRODUCT INVOLVED:

lcon	Venture	Dimension
Icon Classic	Venture Predator	
lcon Weather Shield	Venture Infinity	
Icon Precision Hunter	Venture Dream Season	
Icon Warlord	Venture Weather Shield	
Icon Field	Venture Compact	

REMEDY/ACTION TO BE TAKEN:

STOP USING YOUR RIFLE.

To remedy this condition, your rifle will be inspected and if necessary repaired at no cost to you. Your firearm will be returned as quickly and efficiently as possible. All shipping and repair costs will be covered by Thompson/Center Arms.

Even in the recall condition, the rifle will not fire unless the trigger is pulled. Therefore, always follow these basic firearm safety rules:

- Keep your chamber unloaded until you are ready to shoot.
- Always keep your firearm pointed in a safe direction.
- Never place your finger on the trigger until you have made a conscious decision to fire your rifle.

VERIFICATION OF CORRECTIVE ACTION:

When your rifle is returned, you should note a punch dot on the safety lever. See the photograph below. This punch dot is confirmation that your rifle has been inspected and the hazard has not been found or has been corrected.





When your rifle is returned, you should also note a red star on the label on the outside of your box. See the photograph above. This mark is further confirmation that your rifle has been inspected and the hazard has not been found or has been corrected.